

MODIFICATIONS

June 1996

The reflected power sensing circuits of this transmitter have been modified to provide de-sensing of approximately 3dB to reduce the incidence of power foldback and shutdown arising from inadequacies in the antenna.

Drive Module

R9 3k0 changed to 4k7

Control Module

R67 2k7 changed to 3k9

R56 56k changed to 39k

Surrey Electronics Ltd.,
The Forge, Lucks Green, Cranleigh, Surrey,
GU67BG. Tel: 01483 275997, Fax: 276477.